

Rodamiento de bolas una hilera 510055-PFI - 510055-PFI

<https://www.123rodamiento.es/rodamiento-cojinete/rodamiento-bola/una-hilera/510055-pfi>

PFI Number	PW38700017CSR1
Application	DODGE Atlas 2001-2012, DODGE Attitude 2006-2014, DODGE 110 2012-2014, DODGE Verano 2004-2006, HYUNDAI Accent II 2000-2005, HYUNDAI Accent III 2005-2014, HYUNDAI Alcaz 1996-2004, HYUNDAI Alcaz Prime 1999-2007, HYUNDAI Coupe 1996-2002, HYUNDAI Elantra 1996-2000, HYUNDAI Getz 2002-2009, HYUNDAI i10 2008-2014, HYUNDAI i20 2008-2015, HYUNDAI Lantira II 1995-2000, HYUNDAI Tiburon 1997-2001, KIA Niroving 2004-2011, KIA Picanto 2004-2011, KIA Rio 1 2005-2010, KIA Rio 2 2006-2010
Interchange	FAG 713619510, FAG 713626290, Hyundai 51720-02000, Hyundai 51720-1C000, Hyundai 51720-25000, Hyundai 51720-29300, Hyundai 51720-29400, Kia 51720-02000, NSK 388WD19, SKF 8AHB-636193C, SKF FW178, SKF VKBA367, SKF VKBA491, SKF VKBA7545, SNR R184.05, SNR R189.11, Timken 510055
Description	Wheel Bearing
Position	front wheel
Note	
Inner Diam.	38.100
Outer Diam.	70.000
Width 1	37.000
Width 2	
Weight (kg)	540
Carton Quantity	30
Photo	

CARACTERÍSTICAS DEL PRODUCTO

Marca	PFI
Nº Ean13	3616060914934
Diámetro interior	38 mm
Diámetro exterior	70 mm
Espesor	37 mm
Envasado	1

contacto@123rodamiento.es

911 436 830

CRT4 de Lesquin 60 Rue Du Haut De Sainghin 59273 Fretin FRANCE